

Co/C

Docket No.: TRANS 3.0-053 CIP (PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of: Lopath et al.

Patent No.: 7,189,229

Issued: March 13, 2007

For: BALLOON ALIGNMENT AND COLLAPSING

SYSTEM

Certificate

NOV 1 6 2007

of Correction

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Dear Sir:

Enclosed herewith is a Certificate of Correction with respect to the above-identified U.S. Patent.

The corrections indicated should be made as the application originally filed does not contain such errors. There is no requirement for payment of a fee since the errors were made by the Patent Office.

We look forward to early return of the Certificate of Correction duly certified.

Dated: November 8, 2007

Respectfully submitted,

Marcus J. Millet

Registration No.: 28,241 LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP

KRUMHOLZ & MENTLIK, LLP 600 South Avenue West Westfield, New Jersey 07090 (908) 654-5000

Attorney for Applicant

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _1_ of _1

PATENT NO.

7,189,229

APPLICATION NO.

10/635,170

ISSUE DATE

March 13, 2007

INVENTOR(S)

Patrick David Lopath, Edward Paul Harhen, Yegor Sinelnikov, James D.

Savage, Jaime Merino, and John Hotmer

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, lines 9-10, "the disclosure of which is now U.S. Pat. No. 6,808,524 incorporated by reference herein." should read -- now U.S. Pat. No. 6,808,524, the disclosure of which is incorporated by reference herein. --

Column 13, line 2, "a balljoint surface" should read -- a ball-joint surface --.
Column 13, line 3, "said balljoint surface" should read -- said ball-joint surface --.